Axiom Property Inspections Property Inspection Report



868 Wally Avenue, Henderson NV, 89178 Inspection prepared for: John Doe Agent: David Lawson - Axiom

Inspection Date: 8/12/2010 Time: 2:30 PM Age: Built in 2006 Size: 2372 sq ft Weather: Clear and 94 degrees

Inspector: David Lawson Nevada License #IOS0001580RES



Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed and bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Inspectors final opinion is that with items addressed this is a structurally sound home.

Interior Areas		
Page 3 Item: 6	Doors	• Two door stops are missing. One at front entry door and one missing at the closet door for under stairs area.
Page 3 Item: 7	Electrical	 Cable outlet cover plate missing. Replacement necessary. There are several rooms with wires exposed in ceiling from what appears to be the removal of light fixtures or ceiling fans. A plate must be installed to cover the exposed wire nuts. See photos.
Bathroom		
Page 8 Item: 16	Bath Tubs	Missing stopper noted in master bath tub.
Page 8 Item: 18	Sinks	 Stopper in master bath sink is not connect to stopper lever/pull knob.
Kitchen	-	
Page 9 Item: 3	Dishwasher	• The dishwasher cycled properly, however, there was overflow of drain. Suspect the problem with the overflow is the jammed garbage disposal. Recommend cycling dishwasher after garbage disposal is corrected. If overflow still persists, recommend service by a licensed professional.
Page 9 Item: 5	Garbage Disposal	 Garbage disposal is jammed and will not operate. Recommend repair by licensed professional.
Page 11 Item: 25	Wall Condition	 Missing a piece of baseboard in refrigerator area, In need of repair. We recommend the use of a certified professional.
Garage	-	
Page 17 Item: 1	Roof Condition	 There was only one area of concern on the roof. An improperly cut tile is not properly overlapped by the hip shingle. No visible signs of leaking.
Attic	-	
Page 21 Item: 1	Access	• Batt insulation missing next to access panel. Adding more insulation in area where missing will help protect the indoor area from excessive heat or cold.
Grounds		
Page 25 Item: 7	Grounds Electrical	 Improperly installed switch at water feature. A switch can not be installed in a receptacle cover. In need of correct cover plate.
Page 25 Item: 10	Plumbing	 Gate valve to sprinkler system is corroded and in need of replacement. Water feature in back yard is not functional. Pump is disconnected and was not inspected.

Inspection Details

1. Attendance

In Attendance: Client present • Buyer Agent present

2. Home Type

Home Type: Single Family Home

3. Occupancy

Occupancy: Vacant • The utilities were on at the time of inspection.

Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Bar
Good Fair Poor N/A None
2. Cabinets
Good Fair Poor N/A None
3. Ceiling Fans
Good Fair Poor N/A None Observations:
X • Ceiling fans remaining in house are operational.
4. Closets
Good Fair Poor N/A None
5. Door Bell
Good Fair Poor N/A None
6. Doors
Good Fair Poor N/A None Observations:
X • Two door stops are missing. One at front entry door and one missing at the closet door for under stairs area.
7. Electrical
Good Fair Poor N/A None Observations:
X • Cable outlet cover plate missing. Replacement necessary.
There are several rooms with wires exposed in ceiling from what appears to be the removal of light fixtures or ceiling fans. A plate must be installed to
cover the exposed wire nuts. See photos.
8. Security Bars
Good Fair Poor N/A None
9. Smoke Detectors
Good Fair Poor N/A None

Good Fair Poor N/A None X I I I
11. Window-Wall AC or Heat Good Fair Poor N/A None X X
12. Window Condition Good Fair Poor N/A None X Video Distribution
13. Ceiling Condition Good Fair Poor N/A None X N/A None X Image: A state of the state of
14. Patio Doors
Good Fair Poor N/A None
15. Screen Doors

Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas from being inspected as the inspector will not move personal items.

1. Locations Locations: Master#1 • South East#2 • South West#3 2. Bar Good Fair N/A Poor None Х 3. Cabinets Fair Good Poor N/A None Х 4. Ceiling Fans Good Fair Poor N/A None Observations: Х • All ceiling fans tha were present in the house and porches operated properly. 5. Closets Fair Good Poor N/A None Х 6. Doors Good Fair N/A None Poor Observations: Х Entry door to master bedroom has a split in the edge on the knob side of the door. Split is hairline and door is still operable. 7. Electrical Good Fair Poor N/A None Х 8. Fireplace Good Fair Poor N/A None Х 9. Floor Condition Good Fair Poor N/A None Observations: Х • No cracking noted in tile floors. Carpet is clean and in good condition. 10. Security Bars Good Fair Poor N/A None Х 11. Smoke Detectors Good Fair Poor N/A None Observations: Х • The smoke detectors operated during the inspection.

Page 5 of 30

12. Wall Condition
X Fair Poor N/A None Materials: Drywall walls noted.
13. Window-Wall AC or Heat
Good Fair Poor N/A None
14. Window Condition
Good Fair Poor N/A None X
15. Ceiling Condition
Good Fair Poor N/A None X
16. Patio Doors
Good Fair Poor N/A None X Image: Second Hair Poor N/A None Observations: • The sliding porch/patio door was functional during the inspection.
17. Screen Doors
Good Fair Poor N/A None

Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Locations

Locations: Master Bathroom • Main Floor Bathroom • Upstairs#1

2. Cabinets
Good Fair Poor N/A None
3. Ceiling Condition
Good Fair Poor N/A None Materials: There are drywall ceilings noted.
4. Counters
Good Fair Poor N/A None
5. Doors Good Fair Poor N/A None
6. Electrical Good Fair Poor N/A None
7. GFCI
Good Fair Poor N/A None Observations:
X • GFCI in place and operational
8. Exhaust Fan
Good Fair Poor N/A None Observations:
X • The bath fan was operated and no issues were found.
9. Floor Condition
Good Fair Poor N/A None Materials: Ceramic tile is noted.
10. Heating
Good Fair Poor N/A None
x
11. Mirrors
Good Fair Poor N/A None
Page 7 of 30

12. Plumbing
Good Fair Poor N/A None X Observations: • Shower head in hall bath squeals when running. Operation otherwise is normal.
13. Security Bars Good Fair Poor N/A None
Good Fair Poor N/A None
14. Showers
Good Fair Poor N/A None X
15. Shower Walls
Good Fair Poor N/A None X
16. Bath Tubs
Good Fair Poor N/A None X Image: Stopper noted in master bath tub. Image: Stopper noted in master bath tub.
17. Enclosure
Good Fair Poor N/A None X Image: Source of the shower enclosure was functional at the time of the inspection.
18. Sinks
Good Fair Poor N/A None X Image: Stopper in master bath sink is not connect to stopper lever/pull knob.
19. Toilets
Good Fair Poor N/A None X
20. Window Condition
Good Fair Poor N/A None X Image: A state of the

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Cabinets
Good Fair Poor N/A None
2. Counters
Good Fair Poor N/A None X Observations: • Granite tops noted.
3. Dishwasher
X Observations: • The dishwasher cycled properly, however, there was overflow of drain.
Suspect the problem with the overflow is the jammed garbage disposal.
Recommend cycling dishwasher after garbage disposal is corrected. If overflow still persists, recommend service by a licensed professional.
4. Doors
Good Fair Poor N/A None Observations:
X • No major system safety or function concerns noted at time of inspection.
5. Garbage Disposal
Good Fair Poor N/A None Observations: • Garbage disposal is jammed and will not operate. Recommend repair by
• Garbage disposal is jammed and will not operate. Recommend repair by licensed professional.
6. Microwave
Good Fair Poor N/A None
7. Cook top condition
X Gas cook top noted.
8. Oven & Range
X Observations: • There are two ovens in this home. Both units were functioning properly.
9. Sinks Good Fair Poor N/A None
X
10. Drinking Fountain
Good Fair Poor N/A None

868 Wally Avenue, Henderson, NV

11. Spray Wand
Good Fair Poor N/A None Observations:
X • The spray wand was operated and was functional.
12. Hot Water Dispenser
13. Soap Dispenser
• There was no soap present in the dispenser, could not test.
14. Trash Compactor
Good Fair Poor N/A None
15. Vent Condition
Good Fair Poor N/A None Materials: Exterior Vented
16. Window Condition
Good Fair Poor NA None Materials: Aluminum framed double hung window noted.
17. Floor Condition
Good Fair Poor N/A None Materials: Ceramic tile is noted.
18. Plumbing
Good Fair Poor N/A None Observations:
X • No leaks detected under sink area.
19. Ceiling Condition
Good Fair Poor N/A None Materials: There are drywall ceilings noted.
20. Security Bars
Good Fair Poor N/A None
21. Patio Doors
Good Fair Poor N/A None
22. Screen Doors
Good Fair Poor N/A None

23. Electrical Good Fair Poor N/A None X	
24. GFCI	
Good Fair Poor N/A None	
X	
25. Wall Condition	
Good Fair Poor N/A None	Materials: Drywall walls noted.
X	Observations:
	• Missing a piece of baseboard in refrigerator area, In need of repair. We recommend the use of a certified professional.

A		. .	(•
A XLOM	Pronert	y Inspect	IONS

868 Wally Avenue, Henderson, NV

Laundry
1. Locations
Locations: Down stairs laundry area.
2. Cabinets
Good Fair Poor N/A None
3. Counters Good Fair Poor N/A None
4. Dryer Vent
5. Electrical
X • This house is not equipped with gas line for dryer to attach. Electric dryers
are available for use with this setup.
6. GFCI Good Fair Poor N/A None
7. Exhaust Fan
8. Gas Valves
Good Fair Poor N/A None
9. Wash Basin
Good Fair Poor N/A None
10. Window Condition
Good Fair Poor N/A None Materials: Aluminum framed double hung window noted.
11. Floor Condition
Good Fair Poor N/A None Materials: Ceramic tile is noted.
12. Plumbing Good Fair Poor N/A None

13. Wall Condition Good Fair Poor N/A None X Materials: Drywall walls noted.
14. Ceiling Condition Good Fair Poor N/A None X Materials: There are drywall ceilings noted.
15. Security Bars
Good Fair Poor N/A None

16. Doors

•

Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will test the heating and air conditioner using the thermostat only. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition
Good Fair Poor N/A None Materials: The furnace is located in the attic. Materials: Gas fired forced hot air Observations: • The heating in the home was not inspected due to outside temperature being higher then the manufacturer allows for operating a forced air gas furnace.
2. Heater Base
Good Fair Poor N/A None
3. Enclosure
Good Fair Poor N/A None
4. Venting
Good Fair Poor N/A None
5. Gas Valves
Good Fair Poor N/A None
6. Refrigerant Lines
Good Fair Poor N/A None
7. AC Compress Condition
Good Fair Poor N/A None Compressor Type: electric
X Location: A/C units located outside of the house in the east side yard. Observations:
 This house is equipped with two outside air conditioning units. The units
are both Bryant units. Breakers are properly sized for these units according
to manufacturers name plate. Both units were tested and cooled properly at the time of inspection.
8. Air Supply
Good Fair Poor N/A None

9. R _{Good}	egist _{Fair}	t ers Poor	N/A	None	Observations: • The return air supply system appears to be functional.
10. _{Good}	Filter Fair	'S Poor	N/A	None	Location: Located in a filter grill in a bedroom ceiling.
11. Thermostats					
Good	Fair	Poor	N/A	None	Observations: • Functional at the time of inspection.

Water Heater					
1. Base Good Fair Poor N/A None X Observations: • The water heater base is functional.					
2. Heater Enclosure					
3. Combusion Good Fair Poor N/A None X Observations: • The combustion chamber appears to in functional condition.					
Good Fair Poor N/A None X Image: Second					
5. Water Heater Condition Good Fair Poor N/A None X Heater Type: gas Location: The heater is located in the garage. Observations: • Tank appears to be in satisfactory condition no concerns.					
6. TPRV Good Fair Poor N/A None Observations: X Observations: • Appears to be in satisfactory condition no concerns.					
7. Number Of Gallons Good Fair Poor N/A None X Observations: • HWH is a A.O. Smith, 50 gallon, gas water heater					
8. Gas Valve Good Fair Poor N/A None Observations: X Observational					
9. Plumbing Good Fair Poor N/A None X Description: • No deficiencies observed at the visible portions of the supply piping.					
10. Overflow Condition Good Fair Poor N/A None X Materials: copper					
11. Strapping Good Fair Poor N/A None X					

Garage							
1. Roof Condition							
Good Fair Poor N/A None X A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A A							
2. Walls							
Good Fair Poor N/A None X							
3. Anchor Bolts							
Good Fair Poor N/A None Observations: X • The anchor bolts were not visible.							
4. Floor Condition							
Good Fair Poor N/A None X Materials: Bare concrete floors noted.							
5. Rafters & Ceiling							
Good Fair Poor N/A None							
6. Electrical							
Good Fair Poor N/A None X I I I							
7. GFCI							
Good Fair Poor N/A None X Image: N/A Image: N/A Observations: • Electric subpanel installed in garage.							
8. 240 Volt							
Good Fair Poor N/A None							
9. Exterior Door							
Good Fair Poor N/A None							
10. Fire Door							
Good Fair Poor N/A None X Observations: • Fire door from garage to house has split on the knob edge of the door. Split is hairline. Door still operates and latches properly.							

11 Garage Deer Condition						
11. Garage Door Condition						
Materials: One 16' upgraded insulated steel door						
12. Garage Door Parts						
Good Fair Poor N/A None Observations:						
X • The garage door appeared functional during the inspection.						
13. Garage Opener Status						
Good Fair Poor N/A None Observations:						
X • Screw drive opener noted.						
Appeared functional using normal controls, at time of inspection.						
14. Garage Door's Reverse Status						
Good Fair Poor N/A None Observations:						
X • Eye beam system present and operating.						
15. Ventilation						
Good Fair Poor N/A None						
16. Vent Screens						
Good Fair Poor N/A None						
17. Cabinets Good Fair Poor N/A None						
18. Counters						
Good Fair Poor N/A None						
19. Wash Basin						
Good Fair Poor N/A None						
Good Fair Poor N/A None						
Good Fair Poor N/A None						
Good Fair Poor N/A None						

Electrical							
1. Electrical Panel							
Good Fair Poor N/A None X Image: None Location: Main Location: • Main Disconnect in panel box Location: Located on exterior garage wall. Observations: • No major system safety or function concerns noted at time of inspection at main panel box.							
2. Main Amp Breaker							
Good Fair Poor N/A None X Observations: • 225 Amp main breaker							
3. Breakers in off position							
Good Fair Poor N/A None							
4. Cable Feeds							
Good Fair Poor N/A None X Observations: • Supply cable is underground. Inspector unable to view condition.							
5. Breakers							
5. Breakers							
5. Breakers Good Fair Poor N/A None X All of the circuit breakers appeared serviceable.							
Good Fair Poor N/A None X A A A A Observations: A A A							
Good Fair Poor N/A None X All of the circuit breakers appeared serviceable.							
Good Fair Poor N/A None X All of the circuit breakers appeared serviceable. 6. Fuses Good Fair Poor N/A None							
Good Fair Poor N/A None X All of the circuit breakers appeared serviceable. 6. Fuses Good Fair Poor N/A None							
Good Fair Poor N/A None X All of the circuit breakers appeared serviceable. 6. Fuses Good Fair Poor N/A None							
Good Fair Poor N/A None X All of the circuit breakers appeared serviceable. 6. Fuses Good Fair Poor N/A None							

868 Wally Avenue, Henderson, NV

Roof
1. Roof Condition
X Hair Poor N/A None X Materials: Inspected from ground level with binoculars. Due to property and roof configurations, some areas of the roof may be visually restricted from inspection Materials: Tile roof noted.
2. Flashing
Good Fair Poor N/A None X
3. Chimney
Good Fair Poor N/A None
4. Sky Lights
Good Fair Poor N/A None
5. Spark Arrestor
Good Fair Poor N/A None
6. Vent Caps
Good Fair Poor N/A None
7. Gutter
Good Fair Poor N/A None

Attic						
1. Access						
Good Fair Poor N/A None X Image: Source of the second seco						
2. Structure						
X Bood Fair Poor N/A None Observations: • Wood roof truss framing for roof.						
3. Ventilation Good Fair Poor N/A None X						
4. Vent Screens Good Fair Poor N/A None X						
5. Duct Work						
Good Fair Poor N/A None X Image: N/A Observations: • No missing duct insulation visible from the access panel.						
6. Electrical						
X Deservations: • most not accessible due to insullation						
7. Attic Plumbing						
Good Fair Poor N/A None X						
8. Insulation Condition						
X None Materials: Unfinished fiberglass batts noted. Depth: Insulation averages about 8-10 inches in depth						
9. Chimney						
Good Fair Poor N/A None						
10. Exhaust Vent						
Good Fair Poor N/A None X						

Exterior Areas					
1. Doors					
Good Fair Poor N/A None X					
2. Window Condition					
Good Fair Poor N/A None X					
3. Siding Condition					
Good Fair Poor N/A None X A A A A Observations: A B B B • No major system safety or function concerns noted at time of inspection.					
4. Eaves & Facia					
Good Fair Poor N/A None X I I I I					
5. Exterior Paint					
Good Fair Poor N/A None X					
6. Stucco					
Good Fair Poor N/A None X					

Foundation				
1. Slab Foundation				
Good Fair Poor N/A None X				
2. Foundation Perimeter				
Good Fair Poor N/A None X				
3. Foundation Walls				
Good Fair Poor N/A None X				
4. Cripple Walls				
Good Fair Poor N/A None				
5. Ventilation				
Good Fair Poor N/A None				
6. Vent Screens				
Good Fair Poor N/A None				
7. Access Panel				
Good Fair Poor N/A None				
8. Post and Girders				
Good Fair Poor N/A None				
9. Sub Flooring				
Good Fair Poor N/A None				
10. Anchor Bolts				
Good Fair Poor N/A None X • The anchor bolts were not visible.				
11. Foundation Electrical				
Good Fair Poor N/A None				

12. Foundation Plumbing Good Fair Poor N/A None V V Observations: • **SUPPLY** • 3/4 inch copper

14. Ducting

Good	Fair	Poor	N/A	None
				Х

868 Wally Avenue, Henderson, NV

Grounds
1. Driveway and Walkway Condition
Good Fair Poor N/A None X Image: A structure of the s
Driveway in good shape for age and wear. No deficiencies noted.
2. Grading Good Fair Poor N/A None
X Observations: • The exterior drainage is generally away from foundation.
3. Vegetation Observations
Good Fair Poor N/A None X
4. Gate Condition
Good Fair Poor N/A None Materials: Wrought iron
5. Patio and Porch Deck Good Fair Poor N/A None
6. Stairs & Handrail
Good Fair Poor N/A None
7. Grounds Electrical
Observations: • Improperly installed switch at water feature. A switch can not be installed in a receptacle cover. In need of correct cover plate.
8. GFCI
Good Fair Poor N/A None X
9. Main Gas Valve Condition
$\frac{Good}{Fair}$ Poor N/A None Materials: Located on the garage side of house on exterior.
X Observations: • Serving the purpose for which intened.
10. Plumbing
Good Fair Poor N/A None Materials: Copper piping noted. • PVC piping noted.
X Observations: • Gate valve to sprinkler system is corroded and in need of replacement. • Water feature in back yard is not functional. Pump is disconnected and was not inspected.
11. Water Pressure
Good Fair Poor N/A None Observations: X • 60

12. Pressure Regulator Good Fair Poor N/A None X
13. Exterior Faucet Condition Good Fair Poor N/A None X Location: Gate valve for sprinkler shut off is corroded and in need of replacement
14. Balcony Good Fair Poor N/A None X X
15. Patio Enclosure Good Fair Poor N/A None X
 16. Patio and Porch Condition Good Fair Poor N/A None X None Materials: Lower level porch covered by floor of upstairs porch. Ceiling fan is installed and working properly. • Upper level porch on Master bedroom under tile roof area of main house. Observations: • No major system safety or function concerns noted at time of inspection.
17. Fence Condition Good Fair Poor N/A None X None Materials: Concrete
18. Sprinklers Good Fair Poor N/A None V X Observations: • We do not inspect sprinkler systems.

Photos



GAte valve corroded from leak

Switch incorrectly installed



Disconnected water feature pump

Inoperable water feature



Grilling area with no equipment installed Door stop broken at entry double doors

Page 27 of 30



Broken door stop at door at bottom of stairs

Jammed garbage disposal



Missing base trim at refrigerator area



Bedroom 3 exposed wires on ceiling

Missing cable cover

Fire door to garage has split in end of door

Page 28 of 30



Missing cover



Improperly installed roof tile at hip in front



Master bedroom entry door has split in end of door Exposed electrical wiring needs cover Master bedroom




Bedrooms

Master bedroom sink stopper not connected

Page 29 of 30



Master bath tub stopper missing





Typical attic insulation